

H37. The site driveway onto Orchard Lane is too close to Barandas Drive on the west side of Orchard Lane. This close proximity creates a safety hazard due to left turn conflicts. The driveway cannot be shifted north because it will move into the influence area of the intersection of Orchard Lane and West El Camino Avenue. Therefore the driveway onto Orchard Lane must be eliminated or it must be restricted to ingress and egress of emergency vehicles only.

TO:

Mr. Tran

446-1611 fax

558-6042 telephone

condition for P00-080

from:

Arwen Wachd

808-1964 telephone